

For CIHA Board review April 28, 2022



Miluk Dr. & Mexeye Loop Intersection - Interium Changes

Speed bumps highlighted in yellow are newly proposed.

April 27, 2022

Per CIT Operations Director:

"The location was determined by measuring from the centerline of the yellow speed bump located at the top left of the picture near the three cars, to the end of the double yellow lines located toward the bottom right of the picture near Mexeye Lp. This measurement was divided in half for the location of the new speed bumps. The actual placement was moved a few feet up hill to keep it out of the intersection of the emergency lane to the KWC and Miluk Dr.

Staff have also asked to extend a speed bump down by the Learning Center so that it extends across both lanes."